

Inspection Photos

API: 011-06060

Operator: STRACHAN EXPLORATION INC

Inspection Date: 2/12/2026

County: BENT



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing south along the access road which has not been recontoured and reclaimed.



Inspection Photos



Photo 2. Facing south toward the location. The perennial vegetation is progressing in areas of the location.



Inspection Photos



Photo 3. Facing east where the well was located in the southeast corner. There is less vegetation cover along the west side of the location.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:011-06036 | Date: 2/12/2026

Inspection Photos



Photo 4. Facing southeast where the well was located in the southeast corner. There is less vegetation cover along the west side of the location.



Inspection Photos



Photo 5. Facing toward the northwest side of the location. Vegetation has not established in this area.



Inspection Photos



Photo 6. Facing northwest toward the other road built to access the location.

