

# Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC GRAY B #16 PAD

Location ID: 314562

Date: 02/2/2026



Photo # 1440 Entrance to location

Photo # 1441 Location

## Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC GRAY B #16 PAD

Location ID: 314562

Date: 314562




Photo # 1442 Location




Photo # 1444 Wellhead sign lacks public road used to access the well

## Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC GRAY B #16 PAD

Location ID: 314562

Date: 314562




Photo # 1445 Location




Photo # 1449 SW corner of location

## Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC GRAY B #16 PAD

Location ID: 314562

Date: 314562



Photo # 1450 NW corner of location



Photo # 1451 NE corner of location

# Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC GRAY B #16 PAD

Location ID: 314562

Date: 314562



Photo # 1452 SE corner of location



Photo # 1459 Debris

# Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC GRAY B #16 PAD

Location ID: 314562

Date: 314562




Photo # 1460 Debris



Photo # 1465 Debris

## Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC GRAY B #16 PAD

Location ID: 314562

Date: 314562



Photo # 1466 Debris