

Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC W.P. MELLEN #3A PAD

Location ID: 316619

Date: 02/11/2026



Photo # 2093 Entrance to location

Photo # 2095 Location

Inspection/Audit Photos

Location:

Location ID:

Date:



Photo # 2096 Location

Photo # 2101 Location

Inspection/Audit Photos

Location:

Location ID:

Date:



Photo # 2105 NW corner of location

Photo # 2106 NE corner of location

Inspection/Audit Photos

Location:

Location ID:

Date:



Photo # 2107 SE corner of location



Photo # 2108 SW corner of location