

# Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC HAGOOD M. C. #A 2 PAD

Location ID: 314237

Date: 02/11/2026



Photo # 2120 Entrance to location



Photo # 2124 Location

## Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC HAGOOD M. C. #A 2 PAD

Location ID: 314237

Date: 02/11/2026



Photo # 2125 Location



Photo # 2132 Chemical Labels starting to peel

## Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC HAGOOD M. C. #A 2 PAD

Location ID: 314237

Date: 02/11/2026



Photo # 2135 SW corner of location



Photo # 2136 NW corner of location

## Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC HAGOOD M. C. #A 2 PAD

Location ID: 314237

Date: 02/11/2026



Photo # 2137 NE corner of location



Photo # 2138 SE corner of location

# Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC HAGOOD M. C. #A 2 PAD

Location ID: 314237

Date: 02/11/2026



Photo # 2139 Debris



Photo # 2140 Debris

## Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC HAGOOD M. C. #A 2 PAD

Location ID: 314237

Date: 02/11/2026



Photo # 2141 Debris



Photo # 2142 Debris