

Final Reclamation and Stormwater Inspection

February 13, 2026

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 327248

Well Name: UPRR 38 PAN AM UNIT W #1

Inspection Document #: 718601385

Weld County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: UPRR 38 PAN AM UNIT W #1

Location ID: 327248



Photo 1. Looking south across the well area from the north side. No oil and gas equipment remains.



Photo 2. Photo taken on the west side of the well location in the former turnaround area. Vegetation is not reflective of the surrounding reference area. A higher amount of undesirable weeds such as kochia (*Bassia scoparia*) is present on the location than the surrounding reference area.



Inspection Photos

Location Name: UPRR 38 PAN AM UNIT W #1

Location ID: 327248



Photo 3. Looking west across the wellbore. Some desirable vegetation is present on the well location but it is not reflective of the surrounding reference area. There appears to be less desirable vegetation coverage than the surrounding reference and a higher amount of undesirable weed coverage.



Photo 4. Looking south from the wellbore area. See photo 3 comments.



Inspection Photos
Location Name: UPRR 38 PAN AM UNIT W #1
Location ID: 327248



Feb 13, 2026
80° E
ECMC

Photo 5. Looking east from the wellbore area. See photo 3 comments.



Feb 13, 2026
348° N
ECMC

Photo 6. Looking north from the wellbore area. See photo 3 comments.



Inspection Photos

Location Name: UPRR 38 PAN AM UNIT W #1

Location ID: 327248



Photo 7. Vegetation inside the same pasture as well and tank battery.

