

Final Reclamation and Stormwater Inspection

February 13, 2026

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 305397

Well Name: SILVA #4-13

Inspection Document #: 718601389

Weld County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: SILVA #4-13
Location ID: 305397



Photo 1. Looking south down the access road across the location. The access road remains for nearby active wells.



Photo 2. Looking east from the access road. A rectangle patch that consists of kochia and very limited desirable vegetation is present on location. Patch is approximately 50ft long. See photo 11.



Inspection Photos
Location Name: SILVA #4-13
Location ID: 305397



Photo 3. Looking south on the east side of the road, near the access road. Another longer rectangle patch of kochia is present on location. Very little desirable vegetation is present in the patch and it is not reflective of the vegetation immediately surrounding it.



Photo 4. Looking north across the same patch of kochia as photo 3. See photo 11.



Inspection Photos
Location Name: SILVA #4-13
Location ID: 305397



Photo 5. Looking west across the wellhead area. No oil and gas equipment remains on the location. Desirable perennial vegetation is present and appears to be progressing towards 80% coverage of the reference area. Undesirable weeds such as kochia (*Bassia scoparia*) and cheatgrass (*Bromus tectorum*) are present throughout the location in significant quantities.



Photo 6. Looking south from the wellhead. See photo 5 comments.



Inspection Photos
Location Name: SILVA #4-13
Location ID: 305397



Photo 7. Looking east from the wellhead. See photo 5 comments.



Photo 8. Looking north from the wellhead. See photo 5 comments.



Inspection Photos
Location Name: SILVA #4-13
Location ID: 305397



Photo 9. Looking south across the west side of the location. Desirable perennial vegetation is present. Undesirable weeds such as kochia (*Bassia scoparia*) and cheatgrass (*Bromus tectorum*) are present throughout the location.



Photo 10. Reference area to the east of the well location.



Inspection Photos
Location Name: SILVA #4-13
Location ID: 305397



Photo 11. Google earth aerial imagery taken 06/2010 illustrating max disturbance area and wellhead. Red boxes indicate the patches of kochia.

