

# Inspection Photos

February 3rd, 2026

Operator: Abundance Energy Services

Location ID: 493209

Inspection Document #: 714003475

County: La Plata

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

February 3, 2026  
76° E



**Photo 1.** View of the project area taken from the southern edge facing center.

February 3, 2026  
95° E




**Photo 2.** View of produced water tank label which is not displaying the current operator.

Inspection Photos

Location Name: Hanh Tank Battery

Location ID: 493209



**Photo 3.** Holes/Rips in produced water tank secondary containment berm liner.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources