


QB ENERGY OPERATING LLC MILLER-67S93W 11SWSE Facility # 324070



**QB ENERGY OPERATING LLC
MILLER-67S93W 11SWSE
Facility # 324070**




Label in poor condition.



Condensate label in poor condition.

**QB ENERGY OPERATING LLC
MILLER-67S93W 11SWSE
Facility # 324070**



Fencing material behind tank battery.

**QB ENERGY OPERATING LLC
MILLER-67S93W 11SWSE
Facility # 324070**



Secondary containment full of fluids

**QB ENERGY OPERATING LLC
MILLER-67S93W 11SWSE
Facility # 324070**



Rust around bottom of separator unit.

**QB ENERGY OPERATING LLC
MILLER-67S93W 11SWSE
Facility # 324070**



No smoking sign needs replaced.