

## Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DOUGLAS CREEK UNIT #15 PAD

Location ID: 314969

Date: 02/19/2026



Photo # 2191 Entrance to location



Photo # 2198 Location

## Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DOUGLAS CREEK UNIT #15 PAD

Location ID: 314969

Date: 02/19/2026



Photo # 2192 Location



Photo # 2197 Location

## Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DOUGLAS CREEK UNIT #15 PAD

Location ID: 314969

Date: 02/19/2026



Photo # 2212 SW corner of location



Photo # 2213 SE corner of location

## Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DOUGLAS CREEK UNIT #15 PAD

Location ID: 314969

Date: 02/19/2026



Photo # 2214 NE corner of location



Photo # 2215 NW corner of location