

Inspection Photos

Location Name: LARAMIE ENERGY LLC SHELL 797-09A Pad

Location ID: 335018



Photo # 2678 From entrance to location




Photo # 2679 Location

Inspection Photos

Location Name: LARAMIE ENERGY LLC SHELL 797-09A Pad

Location ID: 335018



Photo # 2680 Location



Photo # 2681 Location

Inspection Photos

Location Name: LARAMIE ENERGY LLC SHELL 797-09A Pad

Location ID: 335018



Photo # 2682 Location




Photo # 2683 Location

Inspection Photos

Location Name: LARAMIE ENERGY LLC SHELL 797-09A Pad

Location ID: 335018



**Photo # 2684 Transducer for SC BH above ground however
valve is buried/not in compliance with CECMC Rule 419**