

Inspection Photos

Location Name: LARAMIE ENERGY LLC CC 0797-05-52 Pad

Location ID: 334774



Photo # 2335 From entrance to location



Photo # 2336 Location

Inspection Photos

Location Name: LARAMIE ENERGY LLC CC 0797-05-52 Pad

Location ID: 334774




Photo # 2337 Location




Photo # 2338 Location

Inspection Photos

Location Name: LARAMIE ENERGY LLC CC 0797-05-52 Pad

Location ID: 334774



Photo # 2339 Location



Photo # 2340 Location

Inspection Photos

Location Name: LARAMIE ENERGY LLC CC 0797-05-52 Pad

Location ID: 334774




Photo # 2341 Unused flowline lacks lockout tagout (OOSLAT)

Photo # 2342 Unused flowline lacks lockout tagout (OOSLAT)