

Inspection Photos  
Location Name: Suckla-Brown Unit 8  
Location ID: 317652



Photo 3 Location.



Photo 4 Wellhead.

Inspection Photos  
Location Name: Suckla-Brown Unit 8  
Location ID: 317652



Photo 3 Wellsite sign faded & needs to be updated.



Photo 4 Ancillary equipment.

Inspection Photos  
Location Name: Suckla-Brown Unit 8  
Location ID: 317652



Photo 5 Wellsite.

Photo 6 Wellsite.