

Inspection Photos

02/23/2026

Operator: QB Energy Operating LLC #10844

Location ID: 334967

Inspection Doc: 719200852

Garfield County, CO

Emily Gaasche
NW Reclamation Specialist
ECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 334967




Photo 1: Photos showing an overview of the location looking north and south, respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 334967



Photo 2: Photos showing an overview of the location looking east and west, respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 334967




Photo 3: Photo showing wellhead signage has slipped downwards, rendering it inconspicuous and difficult to read. Comply with Rule 605.d.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 334967




Photo 4: Photos showing an overview of the northwestern and southwestern interim areas, respectively. Snow cover prevented a full interim inspection; a follow-up inspection will be conducted during future growing seasons to determine 1003 compliance.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources