

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/12/2026

Submitted Date:

02/18/2026

Document Number:

710500727

**FIELD INSPECTION FORM**

Loc ID 439367 Inspector Name: Sanchez, Chris On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10412  
Name of Operator: AUSCO PETROLEUM INC  
Address: 113 N SANTA FE AVENUE  
City: FLORENCE State: CO Zip: 81226

**Findings:**

- 5 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Hart, Tim	309-999-5420	thart@fremontpetroleum.com	<a href="#">All Inspections</a>
Harkins, Liz	719-429-4513	Lharkins@austineexploration.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
439366	WELL	PA	07/31/2025	OW	043-06227	Columbus 1	EI

**General Comment:**

This is a follow up Environmental Inspection for Columbus 1, well location located in Fremont County, Colorado.

API # 05-043-06227  
Location ID 439367  
Pathfinder C-18 8  
Remediation Project # 41043

**Inspected Facilities**

Facility ID: 439366 Type: WELL API Number: 043-06227 Status: PA Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Environmental**

**Spill/Remediation:**

Comment: This is a follow up Environmental Inspection for Remediation Project # 41043. At the time of inspection, an open excavation was observed at the wellhead. Cattle Panels were set in place securing the excavation.

Initial Form 27-I was submitted on 06/18/2025 and approved on 06/30/2025. The approved reporting schedule was identified as 90 days after receipt of analytical. Form 6-S document no. 404300603 indicates the well was cut and capped on 7/31/2025.

Operator shall submit a Supplemental Form 27-S in accordance with the reporting schedule approved in Form 27-I document no. 404300603.

Corrective Action: Previously assigned corrective action date shall apply 01/30/2026 Date: 01/30/2026

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**ECMC Comments**

Comment	User	Date
All ongoing/unaddressed comments, Corrective Actions (CAs) and Conditions of Approval (COAs) from previous Forms remain applicable.	sanchezcc	02/18/2026

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404549156	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7453813">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7453813</a>
710500728	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7453808">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7453808</a>