

Inspection Photos

02/23/2026

Operator: QB Energy Operating LLC #10844

Location ID: 334975

Inspection Doc: 719200854

Garfield County, CO

Emily Gaasche
NW Reclamation Specialist
ECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 334975



Photo 1: Photos showing an overview of the location looking northwest and southeast, respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 334975



Photo 2: Photos showing an overview of the location looking northeast and southwest, respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 334975



Photo 3: Photos showing an overview of the northern and northwestern interim areas, respectively. Perennial grasses are present; however, a follow-up inspection will be conducted during future growing seasons to evaluate 1003 compliance.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 334975



Photo 4: Photos showing southern cut slopes behind separator equipment appear to be predominantly bare or populated by prickly Russian thistle, an undesirable plant species. A follow-up inspection will be conducted during future growing seasons to evaluate 1003 compliance.



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 334975



Photo 5: Photo showing unused fencing and t-posts next to tank equipment; removal is required. Comply with Rule 606.a.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources