

Inspection Photos

API: 071-08637

Operator: OGRIS OPERATING LLC

Inspection Date: 2/23/2026

County: LAS ANIMAS



Inspection Photos



Photo 1. Facing north along the access road toward the location.



Inspection Photos



Photo 2. Facing northwest at the wellsite..



Inspection Photos



Photo 3. Facing south at the north side of the location.



Inspection Photos



Photo 4. Facing southeast at north side of the location. This area of the culvert has been regraded and reseeded.



Inspection Photos



Photo 5. This culvert is filled in with sediment and needs to be cleaned out or replaced..

