

Inspection Photos

API: 071-08733

Operator: OGRIS OPERATING LLC

Inspection Date: 2/23/2026

County: LAS ANIMAS



Inspection Photos



Photo 1. Facing east along the access road toward the location.



Inspection Photos



Photo 2. Well sign is posted at meter shed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:071-08733 | Date: 2/23/2026

Inspection Photos



Photo 3. Facing toward the PW pit.



Inspection Photos



Photo 4. North side of the location facing south. The interim reclamation area is revegetated.

