

Inspection/Audit Photos

Location: SCHUMACHER* JOHN USA--COLO 06412 #2-G well

Location ID: 398876

Date: 02/23/2026



Photo # 2256 Location facing east



Photo # 2259 NE corner of location

Inspection/Audit Photos

Location: SCHUMACHER* JOHN USA--COLO 06412 #2-G well

Location ID: 398876

Date: 02/23/2026



Photo # 2260 Location



Photo # 2263 P&A well

Inspection/Audit Photos

Location: SCHUMACHER* JOHN USA--COLO 06412 #2-G well

Location ID: 398876

Date: 02/23/2026



Photo # 2269 Plugged and abandoned well actively venting gas during inspection.



Photo # 2270 Plugged and abandoned well actively venting gas during inspection.