

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DOUGLAS CREEK UNIT #5 PAD

Location ID: 314298

Date: 02/23/2026



Photo # 2777 Entrance to location



Photo # 2286 Location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DOUGLAS CREEK UNIT #5 PAD

Location ID: 314298

Date: 02/23/2026



Photo # 2278 Location



Photo # 2291 Location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DOUGLAS CREEK UNIT #5 PAD

Location ID: 314298

Date: 02/23/2026



Photo # 2297 SW corner of location



Photo # 2298 NW corner of location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DOUGLAS CREEK UNIT #5 PAD

Location ID: 314298

Date: 02/23/2026



Photo # 2299 NE corner of location



Photo # 2300 SE corner of location