

Inspection Photos

Simcoe/ Mach Natural Resources –Hester Gas Unit - Hester 2, Hester 4.

Location # 334302 - API # 05-067-08494, 05-067-09553

Inspector Name: James Blair. Inspection Date: 02/25/2026

Inspection Doc #: 721100159



01. Well signs for Hester 2 and Hester 4.

Inspection Photos

Simcoe/ Mach Natural Resources –Hester Gas Unit - Hester 2, Hester 4.

Location # 334302 - API # 05-067-08494, 05-067-09553

Inspector Name: James Blair. Inspection Date: 02/25/2026

Inspection Doc #: 721100159



02. Hester 4 wellhead and pumpjack.


Inspection Photos

Simcoe/ Mach Natural Resources –Hester Gas Unit - Hester 2, Hester 4.

Location # 334302 - API # 05-067-08494, 05-067-09553

Inspector Name: James Blair. Inspection Date: 02/25/2026

Inspection Doc #: 721100159



03. Hester 4 wellhead and pumpjack.


Inspection Photos

Simcoe/ Mach Natural Resources –Hester Gas Unit - Hester 2, Hester 4.

Location # 334302 - API # 05-067-08494, 05-067-09553

Inspector Name: James Blair. Inspection Date: 02/25/2026

Inspection Doc #: 721100159



04. Hester 4 produced water tank and secondary containment.

Inspection Photos  
Simcoe/ Mach Natural Resources –Hester Gas Unit - Hester 2, Hester 4.  
Location # 334302 - API # 05-067-08494, 05-067-09553  
Inspector Name: James Blair. Inspection Date: 02/25/2026  
Inspection Doc #: 721100159



05. Hester 4 95 BBL produced water tank and secondary containment.

Inspection Photos

Simcoe/ Mach Natural Resources –Hester Gas Unit - Hester 2, Hester 4.

Location # 334302 - API # 05-067-08494, 05-067-09553

Inspector Name: James Blair. Inspection Date: 02/25/2026

Inspection Doc #: 721100159



06. Inside Hester 4 vertical heated separator structure.

Inspection Photos

Simcoe/ Mach Natural Resources –Hester Gas Unit - Hester 2, Hester 4.

Location # 334302 - API # 05-067-08494, 05-067-09553

Inspector Name: James Blair. Inspection Date: 02/25/2026

Inspection Doc #: 721100159



07. Hester 4 meter run shed.

Inspection Photos

Simcoe/ Mach Natural Resources –Hester Gas Unit - Hester 2, Hester 4.

Location # 334302 - API # 05-067-08494, 05-067-09553

Inspector Name: James Blair. Inspection Date: 02/25/2026

Inspection Doc #: 721100159



08. Inside Hester 4 meter run.


### Inspection Photos

Simcoe/ Mach Natural Resources –Hester Gas Unit - Hester 2, Hester 4.

Location # 334302 - API # 05-067-08494, 05-067-09553

Inspector Name: James Blair. Inspection Date: 02/25/2026

Inspection Doc #: 721100159



09. Hester 4 meter calibration card dated 12/19/2025.

Inspection Photos

Simcoe/ Mach Natural Resources –Hester Gas Unit - Hester 2, Hester 4.

Location # 334302 - API # 05-067-08494, 05-067-09553

Inspector Name: James Blair. Inspection Date: 02/25/2026

Inspection Doc #: 721100159



10. Hester 4 solar telemetry.

Inspection Photos

Simcoe/ Mach Natural Resources –Hester Gas Unit - Hester 2, Hester 4.

Location # 334302 - API # 05-067-08494, 05-067-09553

Inspector Name: James Blair. Inspection Date: 02/25/2026

Inspection Doc #: 721100159



11. Hester 2 wellhead with electric progressive cavity pump.

## Inspection Photos

Simcoe/ Mach Natural Resources –Hester Gas Unit - Hester 2, Hester 4.

Location # 334302 - API # 05-067-08494, 05-067-09553

Inspector Name: James Blair. Inspection Date: 02/25/2026

Inspection Doc #: 721100159



12. Hester 2 wellhead. The wellhead has a progressive cavity pump. It appears to be leaking oil, possibly from the oiler, which is staining the gravel beneath the pump.

Inspection Photos

Simcoe/ Mach Natural Resources –Hester Gas Unit - Hester 2, Hester 4.

Location # 334302 - API # 05-067-08494, 05-067-09553

Inspector Name: James Blair. Inspection Date: 02/25/2026

Inspection Doc #: 721100159



13. Hester 2 wellhead and bradenhead access. Note stained gravel inside of yellow outline.

Inspection Photos

Simcoe/ Mach Natural Resources –Hester Gas Unit - Hester 2, Hester 4.

Location # 334302 - API # 05-067-08494, 05-067-09553

Inspector Name: James Blair. Inspection Date: 02/25/2026

Inspection Doc #: 721100159



14. Hester 2 electric-drive progressive cavity pump. The yellow arrow points at the oil accumulated on rod oiler which is dripping down onto gravel.

Inspection Photos

Simcoe/ Mach Natural Resources –Hester Gas Unit - Hester 2, Hester 4.

Location # 334302 - API # 05-067-08494, 05-067-09553

Inspector Name: James Blair. Inspection Date: 02/25/2026

Inspection Doc #: 721100159



15. Hester 2 produced water with natural gas 21 bbl tank.

Inspection Photos

Simcoe/ Mach Natural Resources –Hester Gas Unit - Hester 2, Hester 4.

Location # 334302 - API # 05-067-08494, 05-067-09553

Inspector Name: James Blair. Inspection Date: 02/25/2026

Inspection Doc #: 721100159



16. Hester 2 21 BBL produced water w. natural gas tank and secondary containment.

## Inspection Photos

Simcoe/ Mach Natural Resources –Hester Gas Unit - Hester 2, Hester 4.

Location # 334302 - API # 05-067-08494, 05-067-09553

Inspector Name: James Blair. Inspection Date: 02/25/2026

Inspection Doc #: 721100159



17. Overview of Hester 2 horizontal heated separator, meter run, and 3' flow lines.

Inspection Photos

Simcoe/ Mach Natural Resources –Hester Gas Unit - Hester 2, Hester 4.

Location # 334302 - API # 05-067-08494, 05-067-09553

Inspector Name: James Blair. Inspection Date: 02/25/2026

Inspection Doc #: 721100159



18. Inside Hester 2 horizontal heated separator.

Inspection Photos

Simcoe/ Mach Natural Resources –Hester Gas Unit - Hester 2, Hester 4.

Location # 334302 - API # 05-067-08494, 05-067-09553

Inspector Name: James Blair. Inspection Date: 02/25/2026

Inspection Doc #: 721100159



19. Wildlife burrows beneath Hester 2 horizontal heated separator structure.

Inspection Photos  
Simcoe/ Mach Natural Resources –Hester Gas Unit - Hester 2, Hester 4.  
Location # 334302 - API # 05-067-08494, 05-067-09553  
Inspector Name: James Blair. Inspection Date: 02/25/2026  
Inspection Doc #: 721100159



XX.

Inspection Photos

Simcoe/ Mach Natural Resources –Hester Gas Unit - Hester 2, Hester 4.

Location # 334302 - API # 05-067-08494, 05-067-09553

Inspector Name: James Blair. Inspection Date: 02/25/2026

Inspection Doc #: 721100159

DATE/ TESTER	METER TESTED	ORIFICE PLATE		GAS SAMPLE	GAS METER DETAIL INSP.
		INSPECT	SIZE		
MJ 7-17-18	YES	YES	1.125	YES	
12.11.19 KC	YES	YES	1.125	YES	
12.22.20 DS	YES	YES	1.125	YES	
11.30.22 KC	YES	YES	1.125 SID	YES	
12-13-23	YES	YES	1.125 SID	YES	
12.19.24 CLS	YES	YES	1.125	YES	
12.19.25 KC	YES	YES	1.125 + 0.875	YES # 2154	

2017

Energy & Carbon Management Commission  
La Plata County  
+37.213060 107.790131  
301° NW  
Feb 25, 2026 at 2:25:25 PM

san juan reproduction 316-46

XX.

Inspection Photos

Simcoe/ Mach Natural Resources –Hester Gas Unit - Hester 2, Hester 4.

Location # 334302 - API # 05-067-08494, 05-067-09553

Inspector Name: James Blair. Inspection Date: 02/25/2026

Inspection Doc #: 721100159



Energy & Carbon Management Commission

La Plata County

+37.213045, -107.790100

11° N

Feb 25, 2026 at 2:26:36 PM

XX.

Inspection Photos

Simcoe/ Mach Natural Resources –Hester Gas Unit - Hester 2, Hester 4.

Location # 334302 - API # 05-067-08494, 05-067-09553

Inspector Name: James Blair. Inspection Date: 02/25/2026

Inspection Doc #: 721100159



XX.

Inspection Photos

Simcoe/ Mach Natural Resources –Hester Gas Unit - Hester 2, Hester 4.

Location # 334302 - API # 05-067-08494, 05-067-09553

Inspector Name: James Blair. Inspection Date: 02/25/2026

Inspection Doc #: 721100159



XX.

Inspection Photos

Simcoe/ Mach Natural Resources –Hester Gas Unit - Hester 2, Hester 4.

Location # 334302 - API # 05-067-08494, 05-067-09553

Inspector Name: James Blair. Inspection Date: 02/25/2026

Inspection Doc #: 721100159



XX.

Inspection Photos

Simcoe/ Mach Natural Resources –Hester Gas Unit - Hester 2, Hester 4.

Location # 334302 - API # 05-067-08494, 05-067-09553

Inspector Name: James Blair. Inspection Date: 02/25/2026

Inspection Doc #: 721100159



XX.

Inspection Photos

Simcoe/ Mach Natural Resources –Hester Gas Unit - Hester 2, Hester 4.

Location # 334302 - API # 05-067-08494, 05-067-09553

Inspector Name: James Blair. Inspection Date: 02/25/2026

Inspection Doc #: 721100159



XX.

Inspection Photos

Simcoe/ Mach Natural Resources –Hester Gas Unit - Hester 2, Hester 4.

Location # 334302 - API # 05-067-08494, 05-067-09553

Inspector Name: James Blair. Inspection Date: 02/25/2026

Inspection Doc #: 721100159



XX.

Inspection Photos

Simcoe/ Mach Natural Resources –Hester Gas Unit - Hester 2, Hester 4.

Location # 334302 - API # 05-067-08494, 05-067-09553

Inspector Name: James Blair. Inspection Date: 02/25/2026

Inspection Doc #: 721100159



 **COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Energy & Carbon Management Commission  
La Plata County  
+37.213017, -107.790174  
175° S  
Feb 25, 2026 at 2:27:22 PM

XX.

Inspection Photos

Simcoe/ Mach Natural Resources –Hester Gas Unit - Hester 2, Hester 4.

Location # 334302 - API # 05-067-08494, 05-067-09553

Inspector Name: James Blair. Inspection Date: 02/25/2026

Inspection Doc #: 721100159



XX.

Inspection Photos

Simcoe/ Mach Natural Resources –Hester Gas Unit - Hester 2, Hester 4.

Location # 334302 - API # 05-067-08494, 05-067-09553

Inspector Name: James Blair. Inspection Date: 02/25/2026

Inspection Doc #: 721100159



XX.