

## Storm Water Management and Erosion control

Location Name: QB ENERGY OPERATING LLC PUCKETT 13B-24D (MESA 17 697) Pad

Location #: 335527



**Location Overview: Location is within High Priority/Black Bear Habitat areas/Greater Sage Grouse General Habitat Management Area & in close proximity to Density Habitat area.**

**Section/Township/Range: 24 6S97W**

# Storm water Management and Erosion control

Location Name: QB ENERGY OPERATING LLC PUCKETT 13B-24D (MESA 17 697) Pad

Location #: 335527

138° SE  
Garfield County



North West corner of location.

252° W  
Garfield County



North East corner of location.

Garfield County



South West corner of location.

Garfield County



South East corner of location.

## Storm water Management and Erosion control

Location Name: QB ENERGY OPERATING LLC PUCKETT 13B-24D (MESA 17 697) Pad

Location #: 335527



Photo # 687 From inspection/audit 708907686 conducted on 10/20/2025 - Failure to maintain chemical BMP – Chemical tank containment approximately 3/4 full of fluid/BMP insufficient to contain possible spill



Photo # 4177 Failure to maintain chemical BMP – Chemical tank containment approximately 3/4 to 7/8 full of fluid/BMP insufficient to contain possible spill

## Storm water Management and Erosion control

Location Name: QB ENERGY OPERATING LLC PUCKETT 13B-24D (MESA 17 697) Pad

Location #: 335527



**Photo # 4178 Failure to maintain chemical BMP – Chemical tank containment approximately 3/4 to 7/8 full of fluid/BMP insufficient to contain possible spill (Additionally the standing fluid on top of the chemical tank containment constitutes a wildlife hazard)**