

Inspection Photos
Location Name: SRC Pratt 24-29D
Location ID: 318975



Photo 1: Wellhead sign

Photo 2: Stained soil

Inspection Photos
Location Name: SRC Pratt 24-29D
Location ID: 318975



Feb 25, 2026 at 9:46:59 AM
+40.017976,-105.032521
321° NW
Weld County
ECMC



Feb 25, 2026 at 9:47:52 AM
+40.018038,-105.032357
264° W
Weld County
ECMC

Photo 3: Tank battery sign

Photo 4: Dead, overgrown vegetation

Inspection Photos
Location Name: SRC Pratt 24-29D
Location ID: 318975



Photo 5: Dead, overgrown vegetation

Photo 6: dead, overgrown vegetation

Inspection Photos
Location Name: SRC Pratt 24-29D
Location ID: 318975



Photo 7: Dead, overgrown vegetation

Photo 8: dead, overgrown vegetation

Inspection Photos
Location Name: SRC Pratt 24-29D
Location ID: 318975



Photo 9: dead, overgrown vegetation

Photo 10: No BBLs displayed

Inspection Photos
Location Name: SRC Pratt 24-29D
Location ID: 318975



Photo 11: No NFPA placard

Photo 12: Dead, overgrown vegetation

Inspection Photos
Location Name: SRC Pratt 24-29D
Location ID: 318975



Photo 13: Dead, overgrown vegetation

Photo 14: dead, overgrown vegetation

Inspection Photos
Location Name: SRC Pratt 24-29D
Location ID: 318975



Photo 15: dead, overgrown vegetation