

Inspection Photos

API: 071-06455

Operator: OGRIS OPERATING LLC

Inspection Date: 2/23/2026

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing west at the location. The access road goes thru the former location and I still in use for the GE #20-14 wellsite.



Inspection Photos



Photo 2. The former location is revegetated and stabilized. The location will need to be recontoured upon access road reclamation in the future.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources