

Inspection Photos

02/27/2026

Operator: QB Energy Operating LLC #10844

Location ID: 334900

Inspection Doc: 719200874

Garfield County, CO

Emily Gaasche
NW Reclamation Specialist
ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 334900



Photo 1: Photos showing an overview of the location looking north and south, respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 334900



Photo 2: Photos showing an overview of the location looking east and west, respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 334900



Photo 3: Photos showing an unmarked guy line anchor located in the southeastern interim area. Comply with Rule 1003.a. and mark or remove anchor.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 334900



Photo 4: Photos showing an overview of the eastern interim area and southwestern cut slopes at the location, respectively. Interim areas are composed of perennial shrubs and grasses and appear to be progressing towards 1003 reclamation requirements.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources