

Inspection Photos
Location Name: Foreman Unit 1
Location ID: 317986



Photo 1 Location entrance.

Photo 2 Wellsite overrun with dead vegetation.

Inspection Photos
Location Name: Foreman Unit 1
Location ID: 317986



Photo 3 Dead vegetation around the wellsite.

Photo 4 Ancillary equipment.

Inspection Photos
Location Name: Foreman Unit 1
Location ID: 317986



Photo 5 Wellsite overrun with dead vegetation.

Photo 6 Pump jack.

Inspection Photos
Location Name: Foreman Unit 1
Location ID: 317986



Photo 9 Wellhead overrun with dead vegetation.