

Final Reclamation Inspection

February 6, 2026

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 327118

Inspection Document #: 718801361

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: HSR-VANNEMAN #3-27A
Location ID: 327118



Photo 1. Photo taken of the well location, facing north. Photo illustrates that final reclamation activities appear to have taken place, but vegetation establishment does not meet Rule 1004 standards. Weedy annual vegetation including russian thistle (*Salsola tragus*) was observed across the location.



Photo 2. Photo taken of the well location, facing east. See comments under Photo 1.

Inspection Photos
Location Name: HSR-VANNEMAN #3-27A
Location ID: 327118



Photo 3. Photo taken of the well location, facing south. See comments under Photo 1.



Photo 4. Photo taken of the well location, facing west. See comments under Photo 1.



Inspection Photos
Location Name: HSR-VANNEMAN #3-27A
Location ID: 327118



Photo 5. Photo taken of ground cover at the well location. Photo illustrates weedy annual vegetation including russian thistle (*Salsola tragus*).



Photo 6. Photo taken of the access road to the location, facing northwest. Photo illustrates that final reclamation activities have taken place along the access road, but vegetation establishment does not meet Rule 1004 standards.

Inspection Photos
Location Name: HSR-VANNEMAN #3-27A
Location ID: 327118



Photo 7. Photo taken of the access road the well location, facing southeast. See comments under Photo 6.



Photo 8. Photo taken of the reference area to the location, south of the location, facing south. Photo illustrates perennial grass and weedy annual vegetation.

