

# Final Reclamation Inspection

February 6, 2026

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 336335

Inspection Document #: 718801353

Weld County, CO

Katelyn Mitchem  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: MAGNESS #16-26A  
Location ID: 336335



**Photo 1.** Photo taken of the well location, facing north. Photo illustrates that final reclamation activities have taken place, but vegetation establishment does not meet Rule 1004 standards at the location or along the access road to the location.



**Photo 2.** Photo taken of the well location, facing east. See comments under Photo 1.



Inspection Photos  
Location Name: MAGNESS #16-26A  
Location ID: 336335



**Photo 3.** Photo taken of the well location, facing south. See comments under Photo 1.



**Photo 4.** Photo taken of the well location, facing west. See comments under Photo 1.



Inspection Photos  
Location Name: MAGNESS #16-26A  
Location ID: 336335



**Photo 5.** Photo taken of ground cover at the location. Photo illustrates perennial grass vegetation and bare ground.



**Photo 6.** Photo taken of the reference area to the location, east of the location, facing northeast. Photo illustrates perennial grass vegetation that has been grazed.

