

Final Reclamation Inspection

February 6, 2026

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 446413

Inspection Document #: 718801339

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: LORENZ L30-3, 5#2-30 O SA

36149578

Location ID: 446413



Photo 1. Photo taken of the tank battery location, facing west. Photo illustrates that final reclamation activities appear to have taken place, but vegetation establishment does not meet Rule 1004 standards. Weedy annual vegetation was observed at the location including kochia (*Bassia scoparia*) and scotch thistle (*Onopordum acanthium*), a List B Noxious Weed species.



Photo 2. Photo taken of the tank battery location, facing east. See comments under Photo 1.



Inspection Photos

Location Name: LORENZ L30-3, 5#2-30 O SA

36149578

Location ID: 446413



Photo 3. Photo taken of the tank battery location, facing south. See comments under Photo 1.



Photo 4. Photo taken of the tank battery location, facing southeast. See comments under Photo 1.



Inspection Photos

Location Name: LORENZ L30-3, 5#2-30 O SA

36149578

Location ID: 446413



Photo 5. Photo taken of vegetation on the location, facing southeast. Photo illustrates perennial grass and weedy annual vegetation including scotch thistle (*Onopordum acanthium*), a List B Noxious Weed species.



Photo 6. Photo taken of the reference area to the location, south of the location, facing south. Photo illustrates perennial grass and weedy annual vegetation.

