

Final Reclamation Inspection

February 6, 2026

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 326783

Inspection Document #: 718801359

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: UPRR 22 PAN AM L #2

Location ID: 326783



Photo 1. Photo taken of the well location, facing north. Photo illustrates that final reclamation activities appear to have taken place at the location, but vegetation establishment does not meet Rule 1004 standards.



Photo 2. Photo taken of the well location, facing east. See comments under Photo 1.



Inspection Photos

Location Name: UPRR 22 PAN AM L #2

Location ID: 326783



Photo 3. Photo taken of the well location, facing south. See comments under Photo 1.



Photo 4. Photo taken of the well location, facing west. See comments under Photo 1.



Inspection Photos

Location Name: UPRR 22 PAN AM L #2

Location ID: 326783



Photo 5. Photo taken of ground cover at the well location. Photo illustrates perennial grass and bare ground.



Photo 6. Photo taken of the reference area to the location, east of the location, facing east. Photo illustrates perennial grass and weedy annual vegetation.

