

Inspection Photos
Kinder Morgan – HB-3
API # 05-083-06549

Inspector Name: James Blair. Inspection Date: 02/27/2026
Inspection Doc #: 721100174



1. Well sign at pad entrance.

Inspection Photos
Kinder Morgan – HB-3
API # 05-083-06549

Inspector Name: James Blair. Inspection Date: 02/27/2026
Inspection Doc #: 721100174



2. Wellhead, cellar, flow line and electrical controls.

Inspection Photos
Kinder Morgan – HB-3
API # 05-083-06549

Inspector Name: James Blair. Inspection Date: 02/27/2026
Inspection Doc #: 721100174



3. Bradenhead in cellar.

Inspection Photos
Kinder Morgan – HB-3
API # 05-083-06549

Inspector Name: James Blair. Inspection Date: 02/27/2026
Inspection Doc #: 721100174



4. Pad overview looking west from entrance. One rig marker is visible.

Inspection Photos
Kinder Morgan – HB-3
API # 05-083-06549

Inspector Name: James Blair. Inspection Date: 02/27/2026
Inspection Doc #: 721100174



6. Flow line and electrical controls.

Inspection Photos
Kinder Morgan – HB-3
API # 05-083-06549

Inspector Name: James Blair. Inspection Date: 02/27/2026
Inspection Doc #: 721100174



6. Pad edge and reclamation vegetation.

Inspection Photos
Kinder Morgan – HB-3
API # 05-083-06549

Inspector Name: James Blair. Inspection Date: 02/27/2026
Inspection Doc #: 721100174



 **COLORADO**
Energy & Carbon Management
Commission
Department of Natural Resources

Energy & Carbon Management Commission
Montezuma County
+37.506421, -108.885308
284° W
Feb 27, 2026 at 3:13:11 PM

7. Pad edge and reclamation vegetation.

Inspection Photos
Kinder Morgan – HB-3
API # 05-083-06549

Inspector Name: James Blair. Inspection Date: 02/27/2026
Inspection Doc #: 721100174



8. Pad edge and reclamation vegetation.

Inspection Photos
Kinder Morgan – HB-3
API # 05-083-06549

Inspector Name: James Blair. Inspection Date: 02/27/2026
Inspection Doc #: 721100174



9. Rig marker in NW corner.

Inspection Photos
Kinder Morgan – HB-3
API # 05-083-06549

Inspector Name: James Blair. Inspection Date: 02/27/2026
Inspection Doc #: 721100174



10. Pad edge and reclamation vegetation.

Inspection Photos
Kinder Morgan – HB-3
API # 05-083-06549

Inspector Name: James Blair. Inspection Date: 02/27/2026
Inspection Doc #: 721100174



11. Pad edge and reclamation vegetation.