


Inspection Photos  
Kinder Morgan – HA #3  
API # 05-083-06383

Inspector Name: James Blair. Inspection Date: 03/02/2026  
Inspection Doc #: 721100186




Energy & Carbon Management Commission  
Montezuma County  
+37.529344,-108.870870  
117° SE  
Mar 2, 2026 at 1:44:34 PM

1. Well sign by entrance to pad near road.

Inspection Photos  
Kinder Morgan – HA #3  
API # 05-083-06383


Inspector Name: James Blair. Inspection Date: 03/02/2026  
Inspection Doc #: 721100186



**2. Wellhead, insulated stainless flowline, electrical controls/telemetry, cathodic protection.**

Inspection Photos  
Kinder Morgan – HA #3  
API # 05-083-06383

Inspector Name: James Blair. Inspection Date: 03/02/2026  
Inspection Doc #: 721100186



Energy & Carbon Management Commission  
Montezuma County  
+37.529237, -108.870321  
313° NW  
Mar 2, 2026 at 1:46:30 PM

3. Flowline and valves, electrical controls, insulated flow line, wellhead.

Inspection Photos  
Kinder Morgan – HA #3  
API # 05-083-06383


Inspector Name: James Blair. Inspection Date: 03/02/2026  
Inspection Doc #: 721100186



**4. Wellhead and bradenhead. Note that gravel surrounding wellhead is raised into a mound and the well cellar is filled in with gravel.**

Inspection Photos  
Kinder Morgan – HA #3  
API # 05-083-06383

Inspector Name: James Blair. Inspection Date: 03/02/2026  
Inspection Doc #: 721100186



5. Overview of well pad from road looking southeast. Rig anchors are marked.

Inspection Photos  
Kinder Morgan – HA #3  
API # 05-083-06383


Inspector Name: James Blair. Inspection Date: 03/02/2026  
Inspection Doc #: 721100186



6. Stormwater ditch and berm fed by culvert from county road.

Inspection Photos  
Kinder Morgan – HA #3  
API # 05-083-06383

Inspector Name: James Blair. Inspection Date: 03/02/2026  
Inspection Doc #: 721100186



7. Well pad and pad margin vegetation between pad and county road.

Inspection Photos  
Kinder Morgan – HA #3  
API # 05-083-06383

Inspector Name: James Blair. Inspection Date: 03/02/2026  
Inspection Doc #: 721100186



**8. Run-on diversion ditch/berm combination. Some earthwork or grading/maintenance appears to have recently been performed on pad.**

Inspection Photos  
Kinder Morgan – HA #3  
API # 05-083-06383

Inspector Name: James Blair. Inspection Date: 03/02/2026  
Inspection Doc #: 721100186



9. Pad margin and interim reclamation area separated by 4-strand barbed wire fence. Rig anchor marker.