

Inspection Photos
Location Name: Gonzales 1-2
Location ID: 320279



Photo 1 Location entrance.

Photo 2 Location.

Inspection Photos
Location Name: Gonzales 1-2
Location ID: 320279



Photo 3 Tank battery.

Photo 4 Tank battery signs.

Inspection Photos
Location Name: Gonzales 1-2
Location ID: 320279




Photo 5 Tank battery.

Photo 6 Separator, Gas Meter Run.

Inspection Photos
Location Name: Gonzales 1-2
Location ID: 320279



Photo 7 Separator, Gas Meter Run.

Photo 8 Wellsite.

Inspection Photos
Location Name: Gonzales 1-2
Location ID: 320279





Photo 9 Wellsite sign.

Photo 10 Wellsite, Master valve appears to have a chain & lock.