

Inspection Photos  
Location Name: Bydalak 1-11  
Location ID: 320191



Photo 1 Location entrance.

Photo 2 Location.

Inspection Photos  
Location Name: Bydalak 1-11  
Location ID: 320191



Photo 3 Wellsite sign.

Photo 4 Wellsite, Master valve appears to have a chain & lock.

Inspection Photos  
Location Name: Bydalak 1-11  
Location ID: 320191



Photo 5 Tank battery.

Photo 6 Tank battery signs.

Inspection Photos  
Location Name: Bydalak 1-11  
Location ID: 320191



Photo 7 Tank battery.

Photo 8 Separator, Gas Meter Run.

Inspection Photos  
Location Name: Bydalak 1-11  
Location ID: 320191



Photo 9 Separator, Gas Meter Run.