

# Inspection Photos

API: 017-06652

Operator: CITATION OIL & GAS CORP

Inspection Date: 3/3/2026

County: CHEYENNE



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing south toward the beginning of the access road. The fence was not installed back to original position and the cattleguard remains.



## Inspection Photos



**Photo 2.** There is a two track road that remains through the pasture.



## Inspection Photos



**Photo 3.** Drone aerial phot where access road turns to the west. The road remains elevated and was not recontoured. The native vegetation has reestablished along the former road.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

API:017-06652 | Date: 3/3/2026

## Inspection Photos



**Photo 4.** Drone aerial photo facing northwest overlooking the location. There is a bermed cut slope that remains along the north and east side shown at red arrow.



## Inspection Photos



**Photo 5.** Facing north overlooking the cutslope which has area that are bare of vegetation.




## Inspection Photos



**Photo 6.** Drone aerial photo facing southwest toward the location.



## Inspection Photos



**Photo 7.** Drone aerial photo facing northeast toward the location.

