

Inspection Photos

02/27/2026

Operator: QB Energy Operating LLC #10844

Location ID: 334834

Inspection Doc: 719200893

Garfield County, CO

Emily Gaasche
NW Reclamation Specialist
ECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 334834



Photo 1: Photos showing an overview of the location looking north and south, respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 334834



Photo 2: Photos showing an overview of the location looking east and west, respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 334834



Photo 3: Photos showing an example of rips/tears that are occurring at the tank's black geotextile liner. Maintenance is required; comply with Rule 603.o.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 334834



Photo 4: Photo showing an example of the northern cut slope; vegetation may need more time to develop. A follow-up inspection will be conducted during future growing seasons to determine compliance with 1003.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 334834



Photo 5: Photos showing an overview of the northern and western interim areas, respectively. Overall, interim areas are progressing towards 1003 reclamation requirements.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 334834



Photo 6: Photos showing examples of vehicle tracking and rutting that is occurring on the working pad surface; gravel appears to be sparse in some places. Comply with Rule 1002.f.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources