

Inspection Photos  
Location Name: Twombly 31-4  
Location ID: 336446



Photo 1 Location entrance.

Photo 2 Location.

Inspection Photos  
Location Name: Twombly 31-4  
Location ID: 336446



Photo 3 Production equipment.

Photo 4 Gas Meter Run, card indicates current calibration.

Inspection Photos  
Location Name: Twombly 31-4  
Location ID: 336446



Photo 5 Tank battery.

Photo 6 Tank battery signs.

Inspection Photos  
Location Name: Twombly 31-4  
Location ID: 336446




Photo 7 Tank battery.

Photo 8 Tank battery.

Inspection Photos  
Location Name: Twombly 31-4  
Location ID: 336446



Photo 9 Multi well pad.

Photo 10 Wellsite sign.

Inspection Photos  
Location Name: Twombly 31-4  
Location ID: 336446



Photo 11 Wellhead.



Photo 12 Wellhead.

Inspection Photos  
Location Name: Twombly 31-4  
Location ID: 336446



Photo 13 Wellhead sign.

Photo 14 Wellhead.

Inspection Photos  
Location Name: Twombly 31-4  
Location ID: 336446




Photo 15 Wellhead.




Photo 16 Wellhead sign.

Inspection Photos  
Location Name: Twombly 31-4  
Location ID: 336446



Photo 17 Wellhead.

Photo 18 Wellhead sign.