

Inspection Photos

March 3rd, 2026

Operator: Simcoe LLC

Location ID: 334274

Inspection Document #: 714003488

County: La Plata

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Huber Kaime 1, 3-12U

March 3, 2026
54° NE



Photo 1. View of the well pad taken from the southern edge facing center.

Inspection Photos
Location Name: Huber Kaime 1, 3-12U

March 3, 2026
336° NW



Photo 2. Surface owner equipment stored on the western edge of the pad.



March 3, 2026
266° W



Photo 3. Surface owner equipment observed on the northern edge of the disturbance.

Inspection Photos
Location Name: Huber Kaime 1, 3-12U

March 3, 2026
218° SW



Photo 4. Surface owner equipment observed on the southern edge of the disturbance.

