

# Inspection Photos

March 3rd, 2026

Operator: Simcoe LLC

Location ID: 325592

Inspection Document #: 714003480

County: La Plata

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Payne 1-8 1

March 3, 2026  
27° NE



**Photo 1.** View of the well pad taken from the southern edge facing north.

March 3, 2026  
52° NE



Photo 2. View of wellhead assembly equipment.

March 3, 2026  
23° NE



**Photo 3.** Surface owner equipment has been removed from the working pad surface.