

Inspection Photos

March 3rd, 2026

Operator: Simcoe LLC

Location ID: 333450

Inspection Document #: 714003492

County: La Plata

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Francis White A2, A4

March 3, 2026
318° NW



Photo 1. View of the well pad taken from the southern edge facing center.

March 3, 2026
31° NE



Photo 2. View of equipment and labels on the eastern edge of the pad.

Inspection Photos
Location Name: Francis White A2, A4

March 3, 2026
27° NE



Photo 3. Surface owner equipment in interim reclamation areas.

Inspection Photos
Location Name: Francis White A2, A4

March 3, 2026
301° NW



Photo 4. Surface owner equipment in interim reclamation areas.

