

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Specialty Resturants Tank Battery

Location ID: 444815 Facility ID: 444816



Photo # 5150 Location



Photo # 5151 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Specialty Resturants Tank Battery

Location ID: 444815 Facility ID: 444816



Photo # 5152 Location



Photo # 5153 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Specialty Resturants Tank Battery

Location ID: 444815 Facility ID: 444816



Photo # 5154 Unused equipment



Photo # 5155 Unused equipment

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Specialty Resturants Tank Battery

Location ID: 444815 Facility ID: 444816



**Photo # 5156 Open ended piping on unused production tank
/wildlife hazard/available for entry by wildlife**



**Photo # 5157 Open ended piping on unused production tank
/wildlife hazard/available for entry by wildlife**

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Specialty Resturants Tank Battery

Location ID: 444815 Facility ID: 444816



**Photo # 5158 Open ended piping on unused production tank
/wildlife hazard/available for entry by wildlife**



**Photo # 5159 Open ended piping on unused production tank
/wildlife hazard/available for entry by wildlife**

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Specialty Resturants Tank Battery

Location ID: 444815 Facility ID: 444816



Photo # 5160 Open ended piping on unused production tank /wildlife hazard/available for entry by wildlife




Photo # 5161 Open ended port on unused production tank/wildlife hazard/available for entry by wildlife

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Specialty Resturants Tank Battery

Location ID: 444815 Facility ID: 444816



Photo # 5162 Open ended port on unused production tank/wildlife hazard/available for entry by wildlife



Photo # 5163 Open ended piping on unused production tank/wildlife hazard/available for entry by wildlife

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Specialty Resturants Tank Battery

Location ID: 444815 Facility ID: 444816



**Photo # 5164 Open ended piping on unused production tank
/wildlife hazard/available for entry by wildlife**



**Photo # 5165 Open ended port on unused production
tank/wildlife hazard/available for entry by wildlife**

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Specialty Resturants Tank Battery

Location ID: 444815 Facility ID: 444816



**Photo # 5166 Open ended piping on unused production tank
/wildlife hazard/available for entry by wildlife**



**Photo # 5167 Open ended piping on unused production tank
/wildlife hazard/available for entry by wildlife**

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Specialty Resturants Tank Battery

Location ID: 444815 Facility ID: 444816



Photo # 5168 Open ended port on unused production tank/wildlife hazard/available for entry by wildlife



Photo # 5169 Open ended piping on unused production tank /wildlife hazard/available for entry by wildlife

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Specialty Resturants Tank Battery

Location ID: 444815 Facility ID: 444816



**Photo # 5170 Open ended piping on unused production tank
/wildlife hazard/available for entry by wildlife**

Photo # 5171 Open ended load line

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Specialty Resturants Tank Battery

Location ID: 444815 Facility ID: 444816



Photo # 5172 Open ended load line



Photo # 5173 Open ended load line

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Specialty Resturants Tank Battery

Location ID: 444815 Facility ID: 444816



Photo # 5174 Open ended load line



Photo # 5175 Open ended load line

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Specialty Resturants Tank Battery

Location ID: 444815 Facility ID: 444816



Photo # 5176 Open ended load line



Photo # 5177 Open ended load line

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Specialty Resturants Tank Battery

Location ID: 444815 Facility ID: 444816



Photo # 5178 Open ended load line



Photo # 5179 Open ended load line

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Specialty Resturants Tank Battery

Location ID: 444815 Facility ID: 444816



Photo # 5180 PRV vent line on separator does not comply with CECMC pressure safety device rules



Photo # 5181 PRV vent line on separator does not comply with CECMC pressure safety device rules

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Specialty Resturants Tank Battery

Location ID: 444815 Facility ID: 444816



Photo # 5182 Burner exhaust stack on separator lacks bird protection



Photo # 5183 Burner exhaust stack on separator lacks bird protection

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Specialty Restaurants Tank Battery

Location ID: 444815 Facility ID: 444816



Photo # 5184 Weeds/undesirable plant species in tank battery secondary containment



Photo # 5185 Weeds/undesirable plant species in tank battery secondary containment

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Specialty Resturants Tank Battery

Location ID: 444815 Facility ID: 444816



Photo # 5186 Weeds/undesirable plant species in tank battery secondary containment



Photo # 5187 Weeds/undesirable plant species in tank battery secondary containment

