



Form Resolution To Document Number: 709100584

Brennan 1 Photo Documentation

Drafted By:



Melissa Parrish

Cell: (970)397-3896

Email: Mparrish@fundareresources.com

Production/ Compliance/ Regulatory/ Health & Safety



Brennan 1 –

Signage Contains Inaccurate Information At Oil & Gas Location. Signage
Contains “Whiting Oil & Gas Inc”.

In Accordance With Rule 605.a. –

Signage Updated to Remove “Whiting Oil & Gas Inc” 12/02/2025

–

Please See Above Photo



Brennan 1 –

Windsack Inadequate/ Repair or Replace Windsack

Windsack Has Been Replaced

–

Please See Above Photo



Brennan 1 –

Trash Observed On Location

In Accordance With Rule 606 –

Trash Cleaned Up, Removed & Properly Disposed Of

–

Please See Above Photo



Brennan 1 –
Burrowing Observed Around Brennan 1 Wellhead (API 123-19400)
Burrowing Around Wellhead Has Been Backfilled
–
Please See Above Photo