

Inspection Photos

API: 017-07209

Operator: CITATION OIL & GAS CORP

Inspection Date: 3/3/2026

County: CHEYENNE



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Drone aerial photo facing southwest at the location. The location has not been recontoured back to the original contour.



Inspection Photos




Photo 2. Facing southwest at the location. The fill material needs to be pushed back into the cut slope.



Inspection Photos



Photo 3. Facing south overlooking the location. The fenced area is not establishing desirable vegetation.



Inspection Photos



Photo 4. Drone aerial photo facing east overlooking the cut slope. This area need to be recontoured and reclaimed.

