

Inspection Photos

API: 017-06918

Operator: CITATION OIL & GAS CORP

Inspection Date: 3/3/2026

County: CHEYENNE



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing west at the location. This area between the two lines has not established desirable vegetation and consists of weeds (Kochia).



Inspection Photos



Photo 2. West side of the location facing east. This area of the location has not established sufficient desirable vegetation.



Inspection Photos



Photo 3. Facing southeast at the location. This area on the left side of the road has also not established desirable vegetation.

