

Inspection Photos
Location Name: Cosslett A 5
Location ID: 318122



Photo 1 Location Access road.




Photo 2 Location/Wellhead.

Inspection Photos
Location Name: Cosslett A 5
Location ID: 318122



Photo 3 Wellhead.

Photo 4 Wellsite.

Inspection Photos
Location Name: Cosslett A 5
Location ID: 318122




Photo 5 Wellhead sign.

Photo 6 Wellsite.

Inspection Photos
Location Name: Cosslett A 5
Location ID: 318122



Photo 7 Ancillary equipment overrun with dead vegetation.