

Inspection Photos
Location Name: State Horth 13-16 OWP
Location ID: 320045



Pic 1 wellhead location, well has been PA

Pic 2 pipeline removed

Inspection Photos
Location Name: State Horth 13-16 OWP
Location ID: 320045



**Pic 3 tank battery has been removed, one tank remains,
ready to be removed.**