

Inspection Photos
Location Name: Box Elder G 42-24 OWP
Location ID: 320565




Pic 1 Unable to access wellhead due to road being washed out

Pic 2 4' washed out part of road going over creek

Inspection Photos
Location Name: Box Elder G 42-24 OWP
Location ID: 320565



Pic 3 washed out road



Pic 4 GPS view of road and wellhead

Inspection Photos
 Location Name: Box Elder G 42-24 OWP
 Location ID: 320565



Pic 5 Tanks

Pic 6 location sign

Inspection Photos
Location Name: Box Elder G 42-24 OWP
Location ID: 320565



Pic 7 separator



Pic 8 GMR riser