

Inspection/Audit Photos

Location: QB ENERGY OPERATING LLC PICEANCE CREEK UNIT #297-11C PAD

Location ID: 398836

Date: 02/25/2026



Photo # 2462 Entrance to location




Photo # 2461 Location sign contains incorrect location ID #

Inspection/Audit Photos

Location: QB ENERGY OPERATING LLC PICEANCE CREEK UNIT #297-11C PAD

Location ID: 398836

Date: 02/25/2026



Photo # 2463 Location



Photo # 2485 Location

Inspection/Audit Photos

Location: QB ENERGY OPERATING LLC PICEANCE CREEK UNIT #297-11C PAD

Location ID: 398836

Date: 02/25/2026



Photo # 2495 SE corner of location



Photo # 2496 SW corner of location

Inspection/Audit Photos

Location: QB ENERGY OPERATING LLC PICEANCE CREEK UNIT #297-11C PAD

Location ID: 398836

Date: 02/25/2026



Photo # 2497 NW corner of location



Photo # 2498 NE corner of location