

# INSPECTION PHOTOS

**Well: APACHE CANYON 18-16**

**API #: 05-071-08928**

**INSPECTION DOC #: 716302010**

**Operator: OGRIS OPERATING LLC 10758**

**Inspection date: 3/5/2026**

**County: Las Animas**



**OGRIS**  
OPERATING, LLC

**719-497-0446**

WDID 912678  
PERMIT 74041

or 911

**Apache Canyon 18-16**  
**SE/SE 18-34S-67W**  
**NAD 83**

**Lat. 37.077042**

**Long. 104.921064**

**API# 05-071-08928**

Network: Mar 6, 2026 at 12:47:44 PM MST  
Local: Mar 6, 2026 at 12:47:44 PM MST  
+37.077225,-104.921135

PHOTO 2: WELL SIGN



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources





Network: Mar 5, 2026 at 1:19:57 PM MST  
Local: Mar 5, 2026 at 1:19:57 PM MST  
+37.076826, -104.921533

PHOTO 3: LOCATION.



Network: Mar 5, 2026 at 1:20:13 PM MST  
Local: Mar 5, 2026 at 1:20:13 PM MST  
+37.077051,-104.921188

PHOTO 4: WELLHEAD AND EQUIPMENT.



**PHOTO 5: AREA OF IMPACTED SOIL NEAR COMPRESSOR. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,(2).D. CA DATE 3/12/2026.**



**PHOTO 6: AREA OF IMPACTED SOIL FROM PRIME MOVER HYDRALIC HOSE. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,(2).D. CA DATE 3/12/2026.**



Network:Mar 5, 2026 at 1:20:13 PM MST  
Local:Mar 5, 2026 at 1:20:13 PM MST  
+37.077051,-104.921188

**PHOTO 7: Vacuum pump observed on well without ECMC approval. Provide ECMC with documentation showing approval of use of vacuum pump. CA DATE 3/24/2026.**



Network:Mar 6, 2026 at 12:47:53 PM MST  
Local:Mar 6, 2026 at 12:47:53 PM MST  
+37.077196,-104.921083

**PHOTO 8: Equipment does not properly prevent wildlife entrance or egress (BIRD PROTECTION). Install or repair wildlife protection equipment PER RULE 608.b.(7). CA DATE 3/12/2026.**



Network: Mar 5, 2026 at 1:23:25 PM MST  
Local: Mar 5, 2026 at 1:23:25 PM MST  
+37-077197-104-921062

**PHOTO 9: Gauge hatch open when not being accessed for gauging or not sealed. Close and seal gauge hatches when not accessing tank per Rule 608. CA DATE 3/7/2026**



**PHOTO 9: OILY WASTE IN PRIME MOVER ENGIN SKID WITHOUT WILDLIFE PROTECTION SCREENS OR NETTING. DRAIN OILY WASTE REPAIR ALL LEAKS AND REMOVE IMPACTED SOIL PER RULE 1002..(2).D & 1002.f.(2)B, Comply with general provisions of the oil and gas act for wildlife protection AND SB-181. CA DATE 24 HOURS TO DRAIN OILY WASTE OR INSTALL WILDLIFE PROTECTION 3/12/2026 FOR ANY IMPACTED SOILS.**