

Final Reclamation Inspection

February 6, 2026

Operator: KERR MCGEE OIL & GAS ONSHORE LP

Location ID: 306134

Inspection Document #: 720300096

Weld County, CO

Isaac Thibedeau
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: SHUR VIEW-65N67W 3NWNW

Location ID: 306134

Feb 6, 2026 at 10:49:16 AM
+40.432726,-104.882778
266° W
Windsor CO 80550
United States



Photo 1. Photo taken from the middle of well location facing west. Bare area and areas of sparse vegetation on the north western corner of location. Vegetation present on location undesirable weeds prodomaly kosha.

Feb 6, 2026 at 10:49:21 AM
+40.432726,-104.882778
356° N
Windsor CO 80550
United States



Photo 2. Photo taken location facing north showing areas of bare soil and undesirable weeds present on well pad.



Inspection Photos

Location Name: SHUR VIEW-65N67W 3NWNW

Location ID: 306134



Photo 3. Photo taken from location facing east towards main access road. Vegetation present undariable kosha.



Photo 4. Photo taken from location facing south. See comments under photo 3.

Inspection Photos

Location Name: SHUR VIEW-65N67W 3NWNW

Location ID: 306134



Photo 5. Photo taken of undesirable vegetation present on location.



Photo 6. Photo taken from location of desirable bunch grass present on location.

Inspection Photos

Location Name: SHUR VIEW-65N67W 3NWNW

Location ID: 306134



Feb 6, 2026 at 10:50:41 AM

+40.432409,-104.882807

9° N

Windsor CO 80550

United States

Photo 7. Photo taken from southeastern edge of location facing north. There is a clear line where well pad was. Where well pad was weeds are present and significant bare areas are present throughout the location.

