

Final Reclamation Inspection

February 6, 2026

Operator: KERR MCGEE OIL & GAS ONSHORE LP

Location ID: 332898

Inspection Document #: 720300097

Weld County, CO

Isaac Thibedeau
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: HSR-KNOX-65N67W 3SWNW

Location ID: 332898



Photo 1. Photo taken from the access road looking down on the location. An attempt to reclaim the access road was made based on evidence of drill seed rows; however, the road has a significant amount of undesirable weeds present, and desirable vegetation is stunted.

Photo 2. Photo taken on the access road going to the location. Weeds are over 4 feet tall and need to be controlled. Additionally, desirable vegetation is stunted, and bare areas are present between drill rows.



Inspection Photos

Location Name: HSR-KNOX-65N67W 3SWNW

Location ID: 332898



Photo 3. Photo taken from access road showing undesirable weeds and bare areas present.



Photo 4. Photo taken from the Easter portion of the location showing undesirable weeds. Evidence of drill-seeded rows with some native grasses present; however, many bare areas remain.

Inspection Photos

Location Name: HSR-KNOX-65N67W 3SWNW

Location ID: 332898



Photo 5. Photo taken on location showing the presence of a List C noxious weed, field bindweed.



Photo 6. Photo taken from eastern side of location facing south west showing large weeds present.

Inspection Photos

Location Name: HSR-KNOX-65N67W 3SWNW

Location ID: 332898



Photo 7. Photo taken from eastern side of location facing west. See comment under photo 6.



Photo 8. Photo taken from eastern side of location facing South. See comment under photo 6.



Inspection Photos

Location Name: HSR-KNOX-65N67W 3SWNW

Location ID: 332898

Feb 6, 2026 at 11:56:10 AM
+40.430828,-104.885254
264° W
Windsor CO 80550
United States



Photo 9. Photo shows desirable grass species that were present on the location, giving some evidence of previous reclamation work; however, undesirable plants outnumber natives significantly.

Feb 6, 2026 at 11:56:12 AM
+40.430828,-104.885254
341° N
Windsor CO 80550
United States



Photo 10. Photo shows undesirable plant species present on location.

